

Surveyed for John Burger Stephen Fields & Fred Hinckbrook
in Sec 13 T7R3 commenced at S E S of Sec 13 run W 120 Ch
to pt Sct by L. J. Wood we then returned 40 Ch and set a
stake then went E 20 Ch and est S ~~set~~ Oak N 80 W 195 1/2 links
Then commenced at SWS and run N 60 vari 8012 Ch and hit
the corner returned S 40.06 Ch and est corner

Black Oak 4 in dia S 60 E 22 links

Then South 20.03 Ch and set a Stone X

G. W. Kellschaw Ch

M. Johnson } the

F. B. Cressy -

Oct-16 Surveyed for Col Bough in Sec 35. T7R3. commenced
at the and run N 50 vari 68 rods and 9 1/2 links across the

branch and est S W Oak 18 in dia North 9 links

Then run E 22 1/4 rods and est S W Oak 6 in dia S 75 E 22 links

Then S 5 vari 68 1/2 rods to the corner of a Stable then W 22 1/4
rods to place of beginning

Isser Rainbolt Ch

J. J. Brandon } the

F. B. Cressy Co Sur

49.
April 6 Surveyed for Abraham Veidleigh in Section 15 T7R5
commenced at the Egt. S run W 79 Ch. The N & S lines I had run
before and when the lines X established as S 39 1/6 Ch W from Egt. S
Ash 5 in dia N 35 1/2 E 46 1/2 links
Ash 6 " " N 1 E 62 " "

We then went East 19.58 Ch and est corner

Sugar 18 in dia N 41 1/2 E 1 rod

Spanish Oak 36 in dia S 27 W 8 1/2 links

Other lines run but not to be recorded

The Owner

John Solidary

F. B. Cressy Co Sur

April 7 Sur for J. Jones & Thom Bland in Sec 10. T7R5.

commenced at Sgt. S and run N 80 3/4 Ch right 6 1/2 links
went back to where the lines X and est d corner

W Oak 24 in dia N 72 W 37 links

Ash 6 " " S 44 E 12 1/2 " } Stone X

Then run E from the center 38.92 Ch then returned 19.46
est corner Poplar 42 in dia S 82 E 8 1/4 links Stone

Elm 16 " " S 50 W 49 " } X

other lines run

F. B. Cressy Co Sur